PRINTED: 09/23/2021 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01			(X3) DATE SURVEY COMPLETED	
					OF - MAIN BOLDING OT	I	R
		445392	B. WING	-		09/	17/2021
NAME OF I	PROVIDER OR SUPPLIER			,	STREET ADDRESS, CITY, STATE, ZIP CODE		
ADAMOE	NACE LLC			′	1927 MEMORIAL BOULEVARD		
ADAMSE	PLACE, LLC			ı	MURFREESBORO, TN 37129		
(X4) ID	SUMMARY STA	ATEMENT OF DEFICIENCIES	ID		PROVIDER'S PLAN OF CORRECTIO	N	(X5)
PREFIX	(EACH DEFICIENC)	Y MUST BE PRECEDED BY FULL	PREFI		(EACH CORRECTIVE ACTION SHOULD		(X5) COMPLETION DATE
TAG	REGULATORY OR L	SC IDENTIFYING INFORMATION)	TAG		CROSS-REFERENCED TO THE APPROP DEFICIENCY)	RIATE	
	1						
(1(000)	INUTIAL COMMENT	T.C.	(IV O	۱۸۸۱			
{K 000}	INITIAL COMMEN	18	{K 0	UU			
	Stories: 2						
		NFPA, II (111); IBC, II					
	protected	-14-					
	Plans available on s Constructed: 1997	site					
	Sprinklered: Yes						
	Census: 83						
	A Life Safety Code	Follow Up Survey was					
	conducted by the S	tate of Tennessee Department					
		of Health Licensure and					
		f Health Care Facilities on					
		his Life Safety Code Survey,					
		was found in substantial					
		e requirements for participation					
		aid at 42 CFR Subpart 483.9, re, and the related National					
		ociation (NFPA) standard					
	101-2012.	ociation (MTT7) standard					
	101 2012.						
	Note: The survey p	rocess was modified during					ì
	this COVID-19 Pub	lic Health Emergency as					
		/ID-19 Emergency Declaration					
		r Health Care Providers and					
	QSO Memo 20-31-	· All.					
	The requirement of	42 (CED) Subport 492 0 in					
	MET as evidenced	: 42 (CFR), Subpart 483.9 is					
	IVIL I as evidenced	by.					
LABORATOR'S	DIRECTOR'S OR PROVID	DER/SUPPLIER REPRESENTATIVE'S SIGI	NATURE		TITLE		(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

PRINTED: 06/17/2021 DEPARTMENT OF HEALTH AND HUMAN SERVICES FORM APPROVED OMB NO. 0938-0391 CENTERS FOR MEDICARE & MEDICAID SERVICES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 - MAIN BUILDING 01 世 B. WING 445392 06/15/2021 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1927 MEMORIAL BOULEVARD ADAMSPLACE, LLC MURFREESBORO, TN 37129 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X5)ID (X4) ID (EACH CORRECTIVE ACTION SHOULD BE COMPLETION (EACH DEFICIENCY MUST BE PRECEDED BY FULL **PREFIX** PRÉFIX CROSS-REFERENCED TO THE APPROPRIATE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) **INITIAL COMMENTS** K 000 K 000 Stories: 2 Construction Type: NFPA, II (111); IBC, II protected Plans available on site Constructed: 1997 Sprinklered: Yes Census: 83 A Life Safety Code Survey was conducted by the State of Tennessee Department of Health Division of Health Licensure and Regulation Office of Health Care Facilities on 6/15/2021. During this Life Safety Code Survey, Adams Place. LLC was found not in substantial compliance with the requirements for participation in Medicare/Medicaid at 42 CFR Subpart 483.9, Life Safety from Fire, and the related National Fire Protection Association (NFPA) standard 101-2012. Note: The survey process was modified during this COVID-19 Public Health Emergency as allowed by the COVID-19 Emergency Declaration Blanket Waivers for Health Care Providers and QSO Memo 20-31- All. The requirement at 42 (CFR), Subpart 483.9 is NOT MET as evidenced by: K 321 | Hazardous Areas - Enclosure K 321 SS=D CFR(s): NFPA 101 Hazardous Areas - Enclosure Hazardous areas are protected by a fire barrier having 1-hour fire resistance rating (with 3/4 hour fire rated doors) or an automatic fire extinguishing system in accordance with 8.7.1 or 19.3.5.9.

Any deficiency statement ending with an asterisk (*) deplotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the payents. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued

Event ID: OV5Y21

program participation.

(X6) DATE

When the approved automatic fire extinguishing

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

PRINTED: 06/17/2021 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01			(X3) DATE SURVEY COMPLETED	
		445392	B. WING			06/	15/2021
	SPLACE, LLC STREET ADDRESS, CITY, STATE, ZIP CODE 1927 MEMORIAL BOULEVARD MURFREESBORO, TN 37129		•				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	BE	(X5) COMPLETION DATE
K 321	separated from othe partitions and doors Doors shall be self-and permitted to ha protective plates the from the bottom of Describe the floor a hazardous areas the 19.3.2.1, 19.3.5.9 Area Separation N/A a. Boiler and Fuel-F b. Laundries (larger c. Repair, Maintena d. Soiled Linen Roce. Trash Collection (exceeding 64 gallof. Combustible Stor (over 50 square feet g. Laboratories (if chazard - see K322) This REQUIREMEN	ed, the areas shall be er spaces by smoke resisting in accordance with 8.4. closing or automatic-closing we nonrated or field-applied at do not exceed 48 inches the door. Indicate a deficient in REMARKS. Automatic Sprinkler A. Fired Heater Rooms of than 100 square feet) ince, and Paint Shops of the sexceeding 64 gallons) Rooms (exceeding 64 gallons) Rooms of the sexceeding 64 gallons) age Rooms/Spaces of the sexceeding feet) ince, and Paint Shops of the sexceeding 64 gallons of the sexceeding 64 gallons, the facility failed to areas.	KS	321			
	1) Observation on 6 revealed that the do services office (beir cleaning solution strubber door stop. NFPA 101, 19.3.2.1	6/15/2021 at 9:58 AM, for to the environmental figured for paper goods and forage,) was held open with a				20	

PRINTED: 06/17/2021 FORM APPROVED OMB NO. 0938-0391

(X3) DATE SURVEY

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	l ' '	TIPLE CONSTRUCTION ING 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED	
		445392	B. WING		06	/15/2021	
NAME OF PROVIDER OR SUPPLIER ADAMSPLACE, LLC			STREET ADDRESS, CITY, STATE, ZIP CODE 1927 MEMORIAL BOULEVARD MURFREESBORO, TN 37129				
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		IOULD BE	(X5) COMPLETION DATE	
K 321	Continued From parevealed that the doclassroom) would in NFPA 101, 19.3.2.1 The Maintenance Description of these deficiencies of Administrator acknowledge of the exit conficulation of Cooking Facilities Cooking Facilities Cooking Facilities Cooking equipment with NFPA 96, Standard Fire Protection Operations, unless: * residential cooking appliances such as toasters) are used to cooking in accordary cooking facilities of compartments with with the conditions or * cooking facilities in 30 or fewer patients 18.3.2.5.4, 19.3.2.5 Cooking facilities proper 9.2.3 are not residential to the cooking facilities of the cooking facilities in 30 or fewer patients 18.3.2.5.4, 19.3.2.5 Cooking facilities proper 9.2.3 are not residential cooking facilities of the cooking facil	ge 2 por to the storage room (by not latch within the frame3 (2012 Edition) Director was present when were identified and the byledged the deficiencies erence on 6/15/2021. It is protected in accordance dard for Ventilation Control of Commercial Cooking g equipment (i.e., small microwaves, hot plates, for food warming or limited ince with 18.3.2.5.2, 19.3.2.5.2 open to the corridor in smoke 30 or fewer patients comply under 18.3.2.5.3, 19.3.2.5.3, in smoke compartments with a comply with conditions under	K3	321			
	corridor. 18.3.2.5.1 through 19.3.2.5.5, 9.2.3, Ti	18.3.2.5.4, 19.3.2.5.1 through A 12-2					

PRINTED: 06/17/2021 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01			(X3) DATE SURVEY COMPLETED		
		445392	B. WING			06/	15/2021	
NAME OF PROVIDER OR SUPPLIER ADAMSPLACE, LLC			STREET ADDRESS, CITY, STATE, ZIP CODE 1927 MEMORIAL BOULEVARD MURFREESBORO, TN 37129					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	BE COMPLÉTION		
K 324 K 511 SS=D	by: Based on interview the cooking facilitie The findings include Interview with kitche 6/15/2021 at 11:30 members were not procedures for fires including: use of hoprimary means of eactivation of the hot 101, 19.3.2.5.2 (20: (2012 Edition) NFPA 96, 10.5.7 (20: The Maintenance Edeficiency was identicated by the conference on 6/15 Utilities - Gas and Equipment using gas complies with NFPA 101 Utilities - Gas and Equipment using gas complies with NFPA electrical wiring and NFPA 70, National Interview with NFPA 101 NFPA 1	NT is not met as evidenced I, the facility failed to protect s. ed: en staff member #1 and #2 on AM, revealed the kitchen staff knowledgeable of proper fire s under the kitchen hood od suppression system as extinguishment and the manual od suppression system. NFPA 12 Edition) NFPA 101, 9.2.3 A 96, 10.2.1 (2011 Edition) Olirector was present when this etified and the Administrator deficiency during the exit //2021. Electric Electric as or related gas piping A 54, National Fuel Gas Code, d equipment complies with Electric Code. Existing intinue in service provided no		511				
	This REQUIREMEN	NT is not met as evidenced						

PRINTED: 06/17/2021 FORM APPROVED OMB NO. 0938-0391

				PLETED		
		445392	B. WING_		06/	15/2021
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 1927 MEMORIAL BOULEVARD MURFREESBORO, TN 37129		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 511	The findings included the following in the state of the finding in the state of t	tions, the facility failed to follow ension cord regulations. ed: 5/2021 at 9:55 AM, revealed environmental services office: d was being used to power a	K 5			

K321

1. It is the policy & procedure that AdamsPlace complies with the applicable building and fire safety regulations. The door stopper was removed on 6/15/21 from the Environmental Services office door. Staff in-service will be conducted the week of 07/05/21 by the Director of Plant Operations related to the regulations regarding the use of using rubber door stops or any object to prop open any door.

2. The storage room door across from the classroom was repaired on 6/18/21 and latches correctly according to guidelines. The Maintenance Director/Assistant will continue to monitor the closing of the storage room doors to ensure they are latching properly.

Completion Date: 7/12/21

K324

It is the policy & procedure that AdamsPlace complies with the applicable building and fire safety regulations. Staff in-service will be conducted the week of 7/05/21 by the Director of Plant Operations & Food Service Director regarding the proper fire procedures for fires under the kitchen hood including use of hood suppression system and the manual activation of hood suppression system. Beginning the week of 7/05/21, a Quality Assurance study will be completed by the Plant Ops Director and Food Service Director weekly for 4 weeks. The Director of Food Services will monitor compliance and report to the facility's Quality Assurance Committee, which consist of the Administrator, Director of Nursing, medical director, one physician, housekeeping supervisor, maintenance supervisor, activity director. Studies and ongoing in-services training will be conducted as determined by the Director of Food Service and Quality Assurance Committee.

Completion date: 7/30/21

K511

- 1. It is the policy & procedure that AdamsPlace complies with the applicable building and fire safety regulations. The extension cord was removed from the Environmental Services Office desk on 6/18/21. Staff in-services will be conducted the week of 07/05/21 by the Director of Plant Operations regarding the use of extension cords. Director of Plant Operations will continue to monitor for compliance.
- 2. The power strip that was plugged into an additional power strip to charge the cleaning equipment was removed on 6/15/21. Staff in-services will be conducted the week of 07/05/21 by the Director of Plant Operations regarding the use of extension cords. Director of Plant Operations will continue to monitor for compliance.

Completion date: 7/12/21

N831

It is the policy & procedure that AdamsPlace complies with the applicable building and fire safety regulations.

- 1. The penetrations by a sprinkler pipe and an empty hole in the rated wall of the electrical room in the service hall corridor have been repaired.
- 2. The penetration by a plumbing pipe in the rated wall of the storage room by the classroom has been repaired.
- 3. The penetration by a metal clad electrical cable and a metal conduit in the rated wall of the 2nd floor mechanical room by the clean linen room has been repaired.
- 4. The synchronization of the fire alarm strobes will be repaired by an outside vendor to stay within the compliance of regulations.

The Director of Plant Operations will continue to monitor for compliance.

Completion date: 7/30/21

Staff hat 7-2-21

PRINTED: 06/17/2021 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED		
		445392	B. WING			06/	15/2021
,	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODI 1927 MEMORIAL BOULEVARD MURFREESBORO, TN 37129		,	
(X4) ID PREFIX TAG			ID PREFI TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
E 000	of Tennessee Depa Health Licensure at Care Facilities surv Life Safety Survey, in substantial comp for participation in M Subpart 483.73, En Note: The survey po this COVID-19 Pub allowed by the COV	ey was conducted by the State artment of Health Division of and Regulation Office of Health ey on 6/15/2021. During this Adams Place, LLC was found bliance with the requirements Medicare/Medicaid at 42 CFR argency Preparedness. Tocess was modified during lic Health Emergency as VID-19 Emergency Declaration and All.	EC	0000			
		EDICHED LED DEDDECENTATIVE'S SIG	MATHE		TITI F		(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Facility ID: TN7501